| Approved For Release 2002/09/03 : C A-RDP78B04747A000100120001-7 | |
|-----------------------------------------------------------------------------------------------------|------|
| | |
| | |
| | |
| Film Processor | |
| | |
| | STAT |
| | STAT |
| Frquent spot checks on this job were made since it is nearing completion and is actually overdue. | STAT |
| has been working strenuously night and day to | STAT |
| complete the machine. All but one of the problems seemed to be solved. The one remaining problem | |
| is the air squeegee which removes the excess moisture | |
| from the film just before it enters the dry box. Unless this is done properly, streaking, mottling | |
| and water spotting result. | STAT |
| A satisfactory 92" air squeegee has never yet been | SIAI |
| made and is having trouble. They sent for help them | STAT |
| cut. All wide film machines use rubber rollers or chamois covered rollers to remove excess moisture | SIAI |
| and prevent droplets from forming just before the | |
| film goes into the dry box. | |
| Since a major virtue is that the emulsion is not touched by other than liquid cr | STAT |
| air from dby-to-dry, an air squeegee must be used. | |
| has a good 35 mm squeegee which can probably be widened to handle 92 film. It will probably | STAT |
| be widened to handle 9th film. It will probably take a 10 horsepower blower to get sufficient air. | |
| | STAT |
| is already a large machine which requires considerable power to run the pumps, blowers and | |
| heaters, but it will run film faster than any exist- ing wide film machine that I know of. | |
| Sensitometric tests have not been run on the thin | |
| positive films which are difficult to handle because | STAT |
| of their very short development time. There is considerable doubt whether this machine can do | STAT |
| satisfactorily. | |
| | |
| | |
| | |
| | |

| | Approved For Release 2002/09/03 : CIA-RDP78B04747A000100120001-7 | |
|------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| | | 8 |
| | | STAT |
| | | STAT |
| STAT | A feview of the contracts and proposals. | |
| STAT | 1. | |
| | Work on this contract is complete. The machine was received back from March AFB where it was undergoing a series of tests. This is the machine to be used in the investigative program on processing factors. The contract is hot closed yet. There is to be a negotiation for the closing of the contract. The negotiation | STAT |
| STAT | ation was postponed until a contract audit was performed. has received no word regarding any action on the audit. They are very anxious to have the audit performed and get the contract closed. If there is anything they can do to speed up action, they would like to do it. The machine is stored at the North end of the plant, adjacent to the area where the investigative program is to be performed. | |
| STAT | is rearranging their facility to accommodate the investigative program. The area to be used is presently occupied by accounting. They have moved engineering to a new-building separate building and rearranged the vacated space to accommodate accounting. | |
| STAT | The pre-contract work to open up the North end of the plant for the proposed work means that they can start right to work on the contract as soon as it is received. The biggest delay will be delivery of the clean room. There doesn't seem to be any way they can get that on order until the contract is received. | |
| STAT | Film Dryer ABD/4. | STAT |
| STAT | This contract is complete and closed out. When made his acceptance inspection, he indicated that although the machine was acceptable there were a number of things that could be improved spend a couple of weeks on the machine. sim- plified it and changed it quite a bit claims that it is working right and tracking properly although I have not seen it run since it was changed. Air re- circulation can now be varied from 0 to 100%. is being stored adjacent and is available for the investigative program. | STAT STAT STAT STAT STAT |
| | | STAT |
| | Approved For Release 2002/09/03 : CIA-RDP78B04747A000100120001-7 | ** |

| Approved For Release 2002/09/03 : CIA-RDP78B04747A00010012 | 20001-7 |
|--------------------------------------------------------------------------------------------------------------------------------------|------------|
| STAT | STAT |
| Please don't have the machine she | it down |
| for anything goes wrong just them to | he |
| speed constal denn to seto, after when | I any |
| speed constal dente to see after when the soull for might have son into can be so figure do it this way it will not count shut down. | as e |
| We've san ese since I.or this afternoon | and |
| so for things harb gone good. That do , | STAT |
| | ight auso. |
| thank you for you congretated | n' i |
| | |
| | STAT |
| | |
| | |